


## REPLANTEO DE CURVA HORIZONTAL # 7 IZQUIERDA



NUMBER	C7
DEFLEXION	28-23-06
RADIO	120.00
LONG. CURVA	59.45
EXTERNAL	3.78
TANGENTE	30.35

